

Tsubaki Advantage Success Stories

Industry Application Name Issue Poor Chain performance Tsubaki was asked to look at the Rexnord bucket elevator chain. The customer was unhappy with the overall performance of the chain. We discussed the benefits of Tsubaki's Workhorse series chain. Workhorse made in the USA chain with higher load ratings then REX. The REX chain had Chinese parts but assembled in the USA. This caused issues with tolerance control. Tsubaki U.S. made chains are made with N.A. sourced Alloy Steels, heat treated & induction hardened pins that result in a higher load rating. The current Rex chain was lasting 2 years. Tsubaki supplied our Workhorse series and was installed in 2017. The chain is still in operation 3 years later. Cost Savings \$50,520 and counting as of 2022-02-21 Item No.: WKHORSE-5856K24L2 Product Type Images Images		,
Application Name Issue Poor Chain performance Tsubaki was asked to look at the Rexnord bucket elevator chain. The customer was unhappy with the overall performance of the chain. We discussed the benefits of Tsubaki's Workhorse series chain. Workhorse made in the USA chain with higher load ratings then REX. The REX chain had Chinese parts but assembled in the USA. This caused issues with tolerance control. Tsubaki U.S. made chains are made with N.A. sourced Alloy Steels, heat treated & induction hardened pins that result in a higher load rating. The current Rex chain was lasting 2 years. Tsubaki supplied our Workhorse series and was installed in 2017. The chain is still in operation 3 years later. Cost Savings \$50,520 and counting as of 2022-02-21 WKHORSE-5856K24L2 Product Type Engineered Class Chain / Workhorse Bucket Elevator Chain		
Issue Poor Chain performance	-	CONSTRUCTION-Aggregate
Tsubaki was asked to look at the Rexnord bucket elevator chain. The customer was unhappy with the overall performance of the chain. We discussed the benefits of Tsubaki's Workhorse series chain. Workhorse made in the USA chain with higher load ratings then REX. The REX chain had Chinese parts but assembled in the USA. This caused issues with tolerance control. Tsubaki U.S. made chains are made with N.A. sourced Alloy Steels, heat treated & induction hardened pins that result in a higher load rating. The current Rex chain was lasting 2 years. Tsubaki supplied our Workhorse series and was installed in 2017. The chain is still in operation 3 years later. Cost Savings \$50,520 and counting as of 2022-02-21 Item No.: WKHORSE-5856K24L2 Product Type Engineered Class Chain / Workhorse Bucket Elevator Chain		Bucket Elevator
Tsubaki Solution Tsubaki U.S. Tsubaki Solution Tsubaki U.S. Tsubaki Solution The current Rex chain was lasting 2 years. Tsubaki supplied our Workhorse series and was installed in 2017. The chain is still in operation 3 years later. Cost Savings \$50,520 and counting as of 2022-02-21 Item No.: WKHORSE-5856K24L2 Engineered Class Chain / Workhorse Bucket Elevator Chain	Issue	Poor Chain performance
Item No.: WKHORSE-5856K24L2 Product Type Engineered Class Chain / Workhorse Bucket Elevator Chain	Tsubaki Solution	was unhappy with the overall performance of the chain. We discussed the benefits of Tsubaki's Workhorse series chain. Workhorse made in the USA chain with higher load ratings then REX. The REX chain had Chinese parts but assembled in the USA. This caused issues with tolerance control. Tsubaki U.S. made chains are made with N.A. sourced Alloy Steels, heat treated & induction hardened pins that result in a higher load rating. The current Rex chain was lasting 2 years. Tsubaki supplied our Workhorse series
Product Type Engineered Class Chain / Workhorse Bucket Elevator Chain	Cost Savings	\$50,520 and counting as of 2022-02-21
	Item No.:	WKHORSE-5856K24L2
Images	Product Type	Engineered Class Chain / Workhorse Bucket Elevator Chain
	Images	